




W3 122 PIN MASS

Input – Wiring View

PINS



Sockets

Pair #	GND	Hot	Cold
1	59	60	61
2	59	60	61
3	56	57	58
4	56	57	58
5	53	54	55
6	53	54	55
7	50	51	52
8	50	51	52
9	37	38	49
10	37	38	49
11	46	47	48
12	46	47	48
13	43	44	45
14	43	44	45

Pair #	GND	Hot	Cold
15	40	41	42
16	40	41	42
17	34	35	36
18	34	35	36
19	31	32	33
20	31	32	33
21	28	29	30
22	28	29	30
23	16	26	27
24	16	26	27
25	23	24	25
26	23	24	25
27	20	21	22
28	20	21	22

Pair #	GND	Hot	Cold
29	17	18	19
30	17	18	19
31	13	14	15
32	13	14	15
33	10	11	12
34	10	11	12
35	7	8	9
36	7	8	9
37	4	5	6
38	4	5	6
39	1	2	3
40	1	2	3

Blue Numbers are Sockets